



Notice #01/2018 (Revision of #01/2017)

Permitted Rudder Area Modification

The ClubSwan 50 Class Authority note the discrepancy in the manufactured detail at the top of the rudder blade(s) and around bearing surface with a gap of up to 10mm to the hull.

This notice gives prior approval under CS50 Class Rule C.6.1(a) for the top of the rudder blade and the rudder bearing area to be modified to achieve the hull / rudder clearance as shown in Figure 2.

A minimum gap of 1mm between the rudder blade and hull must be maintained at all rudder angles & any modification that limits the rotation of the rudder is not permitted.

This modification is not subject to any warranty.

Figure 1 - Current Rudder Blade



Figure 2 – Permitted Addition to Rudder Blade



Andrew Yates
ClubSwan 50 Chief Measurer
10 April 2018